

REPORT of SURVEY for REPAIRS.

26572

No. in Reg. Book. **No.** 578 Survey held at **London** Date **August 5th to 23rd 1864**
 on the **Fr "Ellen"** Master **R. Hughes**
 Tonnage **140** Built at **Conway** When built **1858**
 By whom built _____ Owners **R. Hughes**
 Port belonging to **Carnarvon** Destined Voyage _____
 If Surveyed Afloat or in Dry Dock **Afloat at Katherine's Dock & Docks on Shore Dock.**

Last Survey, No. **1070** Port **Bangor** Classed **11. A. I. 50.**

REPAIRS now done: The Foremast renewed with Red pine, the Windlass unhung & the wood linings stopped; the Fore & After pieces of Main Keelson renewed with English Oak & the Vessel recaulked from Metal-line over all.

Present Condition of the		
Decks Good where seen	Treenails Good where seen	Windlass and Capstan Good
Waterways "	Breasthooks and Stemson "	Pumps "
Comings "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Sails "
Planksheers "	Keelsons Part new	Anchors No. of Sufficient
Sheerstrakes "	Clamps and Shelves "	Cables "
Topsides "	Ceiling "	Hawsers and Warps "
Wales "	Rudder "	Standing & Running Rigging "
Plank (Bottom) and Counter "	Copper When put on	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. **Good where seen**

This Vessel now appears to be in good & efficient condition & is eligible, in our opinion, to remain as classed.

The Amount of Fee.....£ : 10 : - is received by me,

Special.....£ : 3 : 0

Certificate (if required) : 2 : 65.

Committee's Minute **6th January 1865**

Character assigned **11th 1**

second report

R. M. Reed

Thos. W. Hawn



© 2019

Lloyd's Register Foundation

LONB49-0159