

26612

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 62 Survey held at London Date 30th Nov. 1865
on the "Dartmouth" (ship) Master Davies
Tonnage 933 Built at Dundee When built 1859
By whom built Stephen Owners Somes Bros.
Port belonging to London Destined Voyage Sydney
If Surveyed Afloat or in Dry Dock Canal Dry Dock and afloat.

Last Survey, No. 25450 Port London Classed 14.A.1.
63

REPAIRS

Now done. The ship placed in dry dock - hung in shores and caulked to metal line - and her bottom re-sheathed with yellow metal on felt -

Present Condition of the

Decks	<u>good where seen</u>	Treenails	<u>good where seen</u>	Windlass and Capstan	<u>good & efficient</u>
Waterways	"	Breasthooks and Stemson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Sails	"
Planksheers	"	Keelsons	"	Anchors No. of	"
Sheerstrakes	"	Clamps and Shelves	"	Cables	"
Topsides	"	Ceiling	"	Hawsers and Warps	"
Wales	"	Rudder	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	<u>Yellow metal</u> <u>Copper on feet</u> When put on <u>Keel</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She has now been put into good and efficient condition and is in an opinion fit to remain as classed. 14.A.1.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : -

Certificate (if required) : :

Committee's Minute 24th January 1865

Character assigned 14.A.1

record
mt



© 2019

Lloyd's Register
Foundation
LON649-0189