

26640

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 666 Survey held at London Date Dec 21<sup>st</sup> / 64 to Jan 7<sup>th</sup> 18 65  
on the Ship "Goldstream" Master W. D. Kennedy  
Tonnage 756 Built at Maulmain When built 1849  
By whom built \_\_\_\_\_ Owners Teigh & Co  
Port belonging to London Destined Voyage Australia -  
If Surveyed Afloat or in Dry Dock Green's Dry Dock & West India Dock

Last Survey, No. 25819 Port London Classed 12 A 1 13  
font 61. 8 -

## REPAIRS

Now done, The Yellow Metal sheathing stripped off - the Bottom faulted and resheathed with Yellow Metal, the upper course on felt the rest on tarred bottom -  
The Fore & Mizzen rigging refitted -

### Present Condition of the

Decks	}	good	Treenails	}	Windlass and Capstan	}	good		
Waterways			Breasthooks and Stenson		Pumps				
Comings			Transoms, Pointers, and Crutches		Boats				
Upper Deck Beams & Fastenings	}	firm	Timbers of the Frame at the openings	}	Masts, Yards, &c.	}	and		
Lower Deck Beams & Fastenings			Ditto Ditto at other places		Sails				
Planksheers	}	good	Keelsons	}	Anchors No. of	}	3 B. 1 S. 2 K.		
Sheerstrakes			Clamps and Shelves		Cables			}	sufficient
Topsides			Ceiling		Hawsers and Warps				
Wales	}	seen	Rudder	}	Standing & Running Rigging	}			
Plank (Bottom) and Counter			caulked		Copper			Y Mon pr	When put on

### General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested -

She is now in good & efficient condition, fit in my opinion for the safe conveyance of dry and perishable cargoes to, and from all parts of the world and to remain as classed A.1.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : —

Certificate (if required) : :

Committee's Minute 10<sup>th</sup> February 18 65

Character assigned Cond<sup>d</sup> S B 1

Charge £ 1 - 1 -

*Stornick*



© 2019  
Lloyd's Register  
Foundation  
LON649-0211