

REPORT of SURVEY for REPAIRS.

26668

No. in Reg. Book. **No.** 246 Survey held at London Date Feb 20th 1865
 on the Bth "Peterborough" Master Orchard
 Tonnage 500 Built at Sunderland When built 1859
 By whom built _____ Owners Hankey &
 Port belonging to London Destined Voyage China
 If Surveyed Afloat or in Dry Dock Timehouse dry dock & E. Dock

Last Survey, No. 25817 Port London. Classed 13 A 1
 63

REPAIRS

In consequence of damage see Report;
 The yellow metal sheathing stripped, three
 stakes of planking in way of the second futtock
 heads on the port side additionally bolted
 with (about 40 bolts) of yellow metal, the ship
 hung in shores, recaulked from keel to the fifth
 seam of deck inside the waterways; and re-
 sheathed with yellow metal on felt

The vessel as will be seen by the last report had
 only been partially fitted

Present Condition of the

Decks	Good	Treenails	Where seen	Good	Windlass and Capstan	Good & sufficient
Waterways	"	Breasthooks and Stenson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Sails	"
Planksheers	"	Keelsons	"	"	Anchors No. of	"
Sheerstrakes	"	Clamps and Shelves	"	"	Cables	"
Topsides	"	Ceiling	"	"	Hawsers and Warps	"
Wales	"	Rudder	"	"	Standing & Running Rigging	"
Plank (Bottom) and Counter	"	Copper <u>1 1/2</u> When put on <u>now</u>				

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. where tested good

This vessel is now eligible in our opinion
 to remain as classed 13 A 1

The Amount of Fee.....£ : : is received by me,

Special..... 3 : 3 : -

Certificate (if required) : : -

Thos. W. Wawn

Committee's Minute 3rd March 18 65

Character assigned

13 A 1

recorded

MM



© 2019

Lloyd's Register
 Foundation

LON649-0238