

26811

REPORT of SURVEY for REPAIRS.

Dec May -

No. in Reg. Book. **No.** 122 Survey held at London Date March 28th 18 65
on the B^E Wellington Master G Ditchburn
Tonnage 533 Built at Sunderland When built 1847
By whom built _____ Owners Suart & Co
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Limekiln Dock

Last Survey, No. 26022 Port London Classed 10A 1

REPAIRS

Rest 61 — 7 2/64

Yellow metal repaired, recaulked from metal
line to plank sheers -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. Condition, how ascertained.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Plank sheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>1' 4" YMC</u> When put on <u>1844</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where tested

This vessel is eligible in my opinion
to remain classed A 1

The Amount of Fee.....£ : : is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 23rd May 18 65

Character assigned Rest 7 1/2

Thos W. Wawn



© 2019

Lloyd's Register
Foundation

LON649-0368