

26848

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 100 Survey held at London Date May 2nd 18 65
 on the BK "Harmony" Master 107 Linklater
 Tonnage 251 Built at Wt Harmonth When built 1861
 By whom built Fellows Owners J. Spence
 Port belonging to London Destined Voyage Labrador
 If Surveyed Afloat or in Dry Dock in Bridge Dock

Last Survey, No. 25154 Port London - Classed 13 A1
 REPAIRS pt F & D 61 Z 62 c.f. 11. 62

Put on nine strakes of Ice chocks to bow 25ft long of English Oak and Greenheart fastened with Yellow metal bolts and caulked from Line to Planksheer.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. Condition, how ascertained, <u>from enquiry and as seen from deck</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B, 1 S, 1 K.</u>
Sheerstrakes	Clamps and Shells	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>Zinc</u> When put on <u>1862</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where seen Good</u>	

Is now in good and efficient condition and is in our opinion fit to remain as classed

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0

Certificate (if required) : 5 :

John Maxwell
Thos. McNaughton

Committee's Minute 27th June 18 65

Character assigned 13 A1



© 2019

Lloyd's Register
Foundation

LON649 0401