

ANNUAL SURVEYS.

26892

No. 377 Survey held at London Date June 26th 18 65
 on the BK "Fugitive" Master W. Barwood
 Tonnage 471 Built at Sunderland When built 1864
 By whom built Gardner Owners G. B. Walker
 Port belonging to London Destined Voyage Launceston
 If Surveyed Afloat or in Dry Dock in New frame & West India Docks

Last Survey, No. 8179 Port of Sunderland. Classed 10 A1
7.64

The present Condition of the

Decks where seen Good

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails where seen Good

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Do Do at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper F & Y M When put on 1864

Windlass and Capstan Good

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of 3 B, 1 S, 2 K.

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

Committee's Minute 1st August 18 65

Character assigned 10 A 1 mt

John Maxwell

Certificate (if required)

No. 44 Survey held at London Date May 25th 18 65
 on the BK "Queen of Peace" Master Link
 Tonnage 345 Built at Sunderland When built 1863
 By whom built Taylor Owners Barras
 Port belonging to London Destined Voyage Sunderland
 If Surveyed Afloat or in Dry Dock in New frame Dock

Last Survey, No. 7981 Port of Sunderland. Classed 9 A1
12.63

The present Condition of the

Decks where seen Good

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails where seen Good

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the Openings

Do Do at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper Y M When put on 1863

Windlass and Capstan Good

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of 3 B, 1 S, 2 K.

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and is in my opinion fit to remain as classed

Committee's Minute 1st August 18 65

Character assigned 9 A mt

John Maxwell

Certificate (if required).