

26935

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 19 Survey held at London Date 25<sup>th</sup> July to 14<sup>th</sup> Aug<sup>th</sup> 18 65  
on the Barge "Terulau" Master M. H. Frank.  
Tonnage 312 Built at Burton S. When built 1865  
By whom built Dray. Owners Ballard &  
Port belonging to London Destined Voyage Port Natal  
If Surveyed Afloat or in Dry Dock London Dock

Last Survey, No. 3557 Port Hull Classed H. A. I.  
A & C P 65

## REPAIRS

Now done:-

faulked the Main deck from the Poop forward, also the whole of the Poop deck.

## Present Condition of the

Decks <u>faulked</u>	Treenails	Windlass and Capstan
Waterways <u>Leaves faulked</u>	Breasthooks and Stemson	Pumps <u>good</u>
Comings <u>faulked round</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>and</u>
Upper Deck Beams & Fastenings <u>fine</u>	Timbers of the Frame at the openings	Masts, Yards, &c. <u>inquiry</u>
Lower Deck Beams & Fastenings <u>fine</u>	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>from the deck</u>
Planksheers <u>where</u>	Keelsons	Sails <u>sufficient</u>
Sheerstrakes <u>seen</u>	Clamps and Shelves <u>seen</u>	Anchors No. of <u>3. B. 15 &amp; 2 K.</u>
Topsides <u>seen</u>	Ceiling	Cables <u>where</u>
Wales	Rudder	Hawsers and Warps <u>seen</u>
Plank (Bottom) and Counter	Copper <u>F &amp; M.</u> When put on <u>1865</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested.</u>	

She is now in good and efficient condition, and fit, in our opinion, to remain as classed.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : 0

Certificate (if required) .....

Committee's Minute 18<sup>th</sup> August 18 65

Character assigned N/A

Charge for special report on state of decks £1.1.0.



© 2021

Lloyd's Register Foundation

LON 650-0038