

# ANNUAL SURVEYS.

20962

Dec 24/8/62

No. 107 Survey held at London Date August 23<sup>rd</sup> 1865.  
 on the Barque Devonvale Master Charles Brown.  
 Tonnage 283 Built at Alloa When built 1856.  
 By whom built                      Owners Paton & Co.  
 Port belonging to London Destined Voyage Penang.  
 If Surveyed Afloat or in Dry Dock Gun dock

Last Survey, No. 26415 Port of London. Classed G.A. 1.  
bu

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Do Do at other places</u> <u>"</u>	Sails <u>"</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchor's No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>efficient</u> <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Yellow Metal</u> When put on <u>1864</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways good.

Docked for sighting the yellow metal sheathing, which appears unwrinkled and in good condition. She has been scraped bright (before coming into dock) from the Copper line upwards, including the Planksheers and Waterways, but it appears the Owners decline making any further preparation for having her specially surveyed for Confirmation until she returns from her present intended voyage. - I am of opinion she is eligible to remain as classed G.A. 1.

Committee's Minute 25<sup>th</sup> August 1865

Character assigned G.A. 1.

Certificate (if required)

No.                      Survey held at                      Date                      18                      
 on the                      Master                       
 Tonnage                      Built at                      When built                       
 By whom built                      Owners                       
 Port belonging to                      Destined Voyage                       
 If Surveyed Afloat or in Dry Dock                     

Last Survey, No.                      Port of                      Classed                     

The present Condition of the

Decks <u>                    </u>	Treenails <u>                    </u>	Windlass and Capstan <u>                    </u>
Waterways <u>                    </u>	Breasthooks and Stemson <u>                    </u>	Pumps <u>                    </u>
Comings <u>                    </u>	Transoms, Pointers, and Crutches <u>                    </u>	Boats <u>                    </u>
Upper Deck Beams & Fastenings <u>                    </u>	Timbers of the Frame at the Openings <u>                    </u>	Masts, Yards, &c. <u>                    </u>
Lower Deck Beams & Fastenings <u>                    </u>	Keelsons <u>Do Do at other places</u> <u>                    </u>	Sails <u>                    </u>
Planksheers <u>                    </u>	Clamps and Shelves <u>                    </u>	Anchor's No. of <u>                    </u>
Sheerstrakes <u>                    </u>	Ceiling <u>                    </u>	Cables <u>                    </u>
Topsides <u>                    </u>	Rudder <u>                    </u>	Hawsers and Warps <u>                    </u>
Wales <u>                    </u>	Copper <u>                    </u> When put on <u>                    </u>	Standing & Running Rigging <u>                    </u>
Plank (Bottom) and Counter <u>                    </u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways                     

Committee's Minute                      18                    

Character assigned                     

Certificate (if required)



© 2021

Lloyd's Register Foundation

LON 650-0058