

ANNUAL SURVEYS.

20963

Rev 24/8/65

No. 123 Survey held at London Date 8th July 18 65
 on the Ship "Houmahal" Master Howler
 Tonnage 841 Built at Bridport When built 1856
 By whom built Prose Owners Prose
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Comps Dry Dock

Last Survey, No. 26323 Port of London Classed 13. A. 1.
64

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>P. Y. M.</u> When put on <u>1864</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

None done:- Bottom sighted. Sellow Metal patched. faulted from Sellow Metal line to Sheerstrakes. She is now in good and efficient condition, and fit, in our opinion, to remain as classed:- 13. A. 1.

Committee's Minute 25th August 18 65

Character assigned 13 A 1

Certificate (if required)

No. 95 Survey held at London Date 24th July to 25th Aug 18 65
 on the Ship "Oliver Cromwell" Master Balmanno
 Tonnage 527 Built at Aberdeen When built 1847
 By whom built Good Owners Holderness & Co.
 Port belonging to Liverpool Destined Voyage Rangoon
 If Surveyed Afloat or in Dry Dock Ratcliff's Dry Dock

Last Survey, No. 18274 Port of Liverpool Classed 8. Red. A. 1.
SS 63. 47rs.

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Do Do at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>P. S. M.</u> When put on <u>1863</u>	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

None done:- Bottom sighted and Sellow Metal patched:- She was partially loaded with cargo. in the hold. We examined her as far as practicable, and where seen she proved to be in good condition, and is fit, in our opinion, to remain as classed:-

Committee's Minute 25th August 18 65

Character assigned 13 A 1

Certificate (if required)