

REPORT of SURVEY for REPAIRS.

Biennial Survey.

No. in Reg. Book. **No.** 302 Survey held at London Date Oct^r 18th 23rd 1865
 on the Ship Black Prince Master W. Inglis.
 Tonnage 750 Built at Aberdeen When built 1863.
 By whom built Hall Owners Finlay & Co.,
 Port belonging to London Destined Voyage Hong Kong.
 If Surveyed Afloat or in Dry Dock "Nelson"

Last Survey, No. 2129 Port Aberdeen. Classified Ex^{pl} B.S. 13.A.1.
 63

REPAIRS

Stripped off the Copper Sheathing, lifted the timbers, opened her on the Starb^d side at the turn of bilge inside, examined the Ribs, fastenings, &c. — Drifted out one of the galvaniz'd iron bolts, from below the Copper line, and found it unsatisfactory or wasted. Recommended that more be driven out for inspection. which has been done, and the whole of them proved in a much better state, or but little wasted. — payed the bottom with Stockholm Tar. Resheathed with Copper on dry paper up to 19 ft. —

Present Condition of the

Decks	<u>in good order</u>	Freemasts	<u>Galvaniz'd bolts where seen</u>	Windlass and Capstan	<u>in good order</u>
Waterways	"	Breasthooks and Stenson	<u>good</u>	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	<u>firm</u>	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	"
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchor No. of <u>2</u>	"
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	<u>efficient</u>	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<u>on paper</u> When put on <u>now.</u>	Standing & Running Rigging	"
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>				

I am of opinion this Vessel is entitled to remain
 as class'd "Ex^{pl} B.S."
 13.A.1.

The Amount of Fee.....£..... is received by me,

Special..... 2 : 2 :

Certificate (if required)

Committee's Minute 31st October 18 65

Character assigned

13 A 1

rec'd Copper

Samuel Wilson,
 " "



© 2021

Lloyd's Register
 Foundation

LON 650-0157

Black Primer

REPORT OF SURVEY FOR REPAIRS



© 2021

Lloyd's Register
Foundation