

REPORT of SURVEY for REPAIRS.

27109

No. in ^{the} 142 No. 142 Survey held at London Date Oct 10th 1865
on the S. + Eliza Shaw Master J. Steele
 Tonnage 696 Built at Glasgow When built 1863
 By whom built _____ Owners C. Shaw
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Green's Lower Dock

Recd 11/11/65

Survey, No. 26538 Port London Classed 15. A. I.
 Iron Frame planked Ex 185 10.64

REPAIRS Now done:

The Yellow Metal sheathing stripped,
 the vessel re-caulked from keel to metal-line,
 and re-sheathed with Yellow Metal over felt.

Present Condition of the

Decks <u>Good where seen</u>	Bolts <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways "	Breasthooks and Stemson "	Pumps "
Comings "	Transoms, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame at the openings "	Masts, Yards, &c. <u>by rigging" & inspection</u>
Lower Deck Beams & Fastenings "	Ditto Ditto at other places "	Sails <u>Sufficient</u>
Planksheers "	Keelsons "	Anchors No. of "
Sheerstrakes "	Clamps and Shelves "	Cables "
Topsides "	Ceiling "	Hawsers and Warps "
Wales "	Rudder <u>L. J. M.</u> When put on <u>Good</u>	Standing & Running Rigging "
Plank (Bottom) and Counter "		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested.

This vessel appears to be in good and
 efficient condition, and eligible, in my opinion,
 to remain as classed. — 15. A. I.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0.

Certificate (if required) : : :

Committee's Minute 24th November 18 65

Character assigned 15 A I

MA record

R. J. Reed.
John Rawell



© 2021

Lloyd's Register
 Foundation

LOW 650-0192