

27140

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 374 Survey held at London Date July 15<sup>th</sup> 20<sup>th</sup> 1865  
on the BK "Priscilla" Master W. Brown  
Tonnage 253 Built at Wells When built 1858  
By whom built \_\_\_\_\_ Owners Bullard & Co  
Port belonging to London Destined Voyage Natal  
If Surveyed Afloat or in Dry Dock Lavender Dry Dock

Last Survey, No. 25273 Port London. Classed 10 A.1.  
63

## REPAIRS

Now done, the Bottom faulted and resheathed with Yellow Metal upon felt -

### Present Condition of the

Decks	} good where seen	Treenails	} good where seen	Windlass and Capstan	} good and efficient where seen
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers	} seen	Keelsons	} seen	Sails	} seen
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper <u>ILYM</u> When put on <u>now</u>		Standing & Running Riggings	

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now in good and efficient condition fit in my opinion to remain as classed A.1.

The Amount of Fee.....£ : : is received by me,  
Special..... 1 : 1 :  
Certificate (if required) : 5 : -

Committee's Minute 15<sup>th</sup> December 1865

Character assigned 10 A.1  
record