

REPORT of SURVEY for REPAIRS.

27151

No. in Reg. Book. **No.** 671 Survey held at London Date 22nd Nov^r 5th Dec^r 1865
 on the Brig "Matilda" Master John Ridland
 Tonnage 239 Built at Bristol When built 1850
 By whom built _____ Owners Scrutton Sons & Co
 Port belonging to Bristol Destined Voyage West India
 If Surveyed Afloat or in Dry Dock Union Dry Dock and West India Dock

Last Survey, No. 25747 Port London Classed 12 A 1
C. 62.8 yrs.

REPAIRS

Now done:-

The Bottom sighted and the Yellow metal patched. - Renewed the whole of the Upper deck with Red-pine, and the upper deck framings and Headledges with American and Dantzic Oak.

Present Condition of the

Deck <u>new</u>	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stenson	Pumps
Comings <u>new</u>	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places <u>where</u>	Condition, how ascertained <u>By inquiry and observation from the deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>T. A. M.</u> When put on <u>1863</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways <u>good where seen</u>	

She is now in good and efficient condition, and fit, in my opinion, to remain as classed.

Williamson

The Amount of Fee.....£ 10 is received by me.

Special..... 1 : 1 : 1

Certificate (if required) : :

Committee's Minute 19th December 18 65

Character assigned Cont^d 8/12

record repair



© 2021

Lloyd's Register Foundation

LON 650-0228