

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 780 Survey held at London Date July 11th to Aug 2nd 1865
 on the Ship "Ethereal" Master A. Anderson
 Tonnage 214 Built at Hartlepool When built 1856
 By whom built _____ Owners Park Bros
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Nelson Dry Dock East India Dock.

Last Survey, No. 2201 Port Stockton Classed 10 A.1.
 62

REPAIRS

Now done, the Yellow Metal Stripped, faulted from the keel to the waterway beam, and a portion of the upper deck, and the Bottom resheathed with Yellow Metal upon Felt ~

The upper course of bottom was dabbled bright and a few treenails driven out for survey in anticipation of fortification, but before the plank or holes could be examined the Owner declined our specially surveying the part named, and it was metalled over without our doing so ~

Present Condition of the

Decks <u>pt Caulked</u>	Treenails <u>those seen good</u>	Windlass and Capstan	} <u>good</u>
Waterways <u>Caulked</u>	Breasthooks and Stemson	Pumps	
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats	} <u>and</u>
Upper Deck Beams & Fastenings <u>where</u>	Timbers of the Frame at the openings <u>where</u>	Masts, Yards, &c.	
Lower Deck Beams & Fastenings <u>where</u>	Ditto Ditto at other places <u>where</u>	Sails	} <u>Sufficient</u>
Planksheers <u>Caulked</u>	Keelsons	Anchors No. of	
Sheerstrakes <u>dr</u>	Clamps and Shelves <u>seen</u>	Cables	} <u>where</u>
Topsides <u>dr</u>	Ceiling	Hawsers and Warps	
Wales <u>d</u>	Rudder	Standing & Running Rigging	} <u>seen</u>
Plank (Bottom) and Counter <u>Caulked</u>	Copper <u>F.L.M.</u> When put on <u>now</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

good where tested
 She is now in good condition, fit in our opinion to remain as classed 10 A.1.

The Amount of Fee.....£..... is received by me,

Special..... 1 : 1 : 7 } 10/2/66

Certificate (if required) 5 : }

Committee's Minute 13th February 18 66

Character assigned 10 A.1 record VM

Charge £1.1. MA



© 2021

Lloyd's Register Foundation