

27259

REPORT of SURVEY for REPAIRS.

No. in Book. **No.** 153 Survey held at London. Date 3rd to 7th Feb'y. 18 66.
on the Ship "Scorpetown" Master A. Pollard.
Tonnage 414 Built at Sunderland When built 1858
By whom built _____ Owners Javan Bros.
Port belonging to London. Destined Voyage Barbadoes.
If Surveyed Afloat or in Dry Dock Bridge Dry Dock.

Last Survey, No. 25730 Port London. Classed 11. A. 1
68

REPAIRS
Now done:-
Copper stripped off the Bottom, and
caulked from keel to the Plank Sheer, and resheathed
the Bottom with Copper on Brown-paper.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stemson		Pumps	
Comings	<u>good</u>	Transoms, Pointers, and Crutches	<u>good</u>	Boats <u>3 No.</u>	<u>good where seen.</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	<u>where</u>	Ditto Ditto at other places	<u>where</u>	Condition, how ascertained <u>By inquiry & observation.</u>	
Plank sheers		Keelsons		Sails	
Sheerstrakes	<u>faulked.</u>	Clamps and Shelves	<u>seen.</u>	Anchors No. of	<u>good and</u>
Topsides	<u>seen.</u>	Ceiling		Cables	<u>sufficient</u>
Wales		Rudder		Hawsers and Warps	<u>where seen.</u>
Plank (Bottom) and Counter	<u>faulked.</u>	Copper on brown-paper When put on	<u>now</u>	Standing & Running Rigging	
General Observations and Opinion;		Caulking of Bottom, Deck, & Waterways.	<u>good where tested.</u>		

She is now in good and efficient condition,
and fit, in my opinion, to remain as classed.
Williamson.

The Amount of Fee.....£ : : is received by me,
Special..... / : / :
Certificate (if required) : 5 :
11/2

Committee's Minute 16th February 18 66

Character assigned second Copper
W.H.