

# ANNUAL SURVEYS.

27289

No. 468 on the 8 " John Temperley Master R Liddle Date Feb 26<sup>th</sup> 18 66  
 Tonnage 976 Built at Sunderland When built 1856  
 By whom built Halls Owners Temperley  
 Port belonging to London Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock in Regent & East India Dock

Rev 26/2/66  
 25

Last Survey, No. 26757 Port of London.

Classed 13A  
 A 9CP 2.65

The present Condition of the

Decks where seen Good  
 Waterways " " "  
 Comings " " "  
 Upper Deck Beams & Fastenings " " "  
 Lower Deck Beams & Fastenings " " "  
 Planksheers " " "  
 Sheerstrakes " " "  
 Topsides " " "  
 Wales " " "  
 Plank (Bottom) and Counter " " "

Treenails where seen Good  
 Breasthooks and Stemson " " "  
 Transoms, Pointers, and Crutches " " "  
 Timbers of the Frame at the Openings " " "  
 Do Do at other places " " "  
 Keelsons not seen  
 Clamps and Shelves " " "  
 Ceiling " " "  
 Rudder " " "  
 Copper F.Y.M. When put on 1865

Windlass and Capstan Good  
 Pumps "  
 Boats "  
 Masts, Yards, &c. "  
 Sails "  
 Anchors No. of 3 D, 1 S, 1 K  
 Cables "  
 Hawsers and Warps "  
 Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Is now in good and efficient condition and is in our opinion fit to remain as classed.

John Maxwell  
 R. J. Reed

Committee's Minute 27 February 18 66  
 Character assigned 13A 1

Certificate (if required)

No. 58 on the 2 " Dartmouth Master Davies Date Feb 26<sup>th</sup> 18 66  
 Tonnage 933 Built at Dundee When built 1859  
 By whom built Stephen Owners Somes  
 Port belonging to London Destined Voyage  
 If Surveyed Afloat or in Dry Dock in Regent & East India Dock

Last Survey, No. 26612 Port of London.

Classed 11A  
 1.65

The present Condition of the

Decks where seen Good  
 Waterways " " "  
 Comings " " "  
 Upper Deck Beams & Fastenings " " "  
 Lower Deck Beams & Fastenings " " "  
 Planksheers " " "  
 Sheerstrakes " " "  
 Topsides " " "  
 Wales " " "  
 Plank (Bottom) and Counter " " "

Treenails where seen Good  
 Breasthooks and Stemson " " "  
 Transoms, Pointers, and Crutches " " "  
 Timbers of the Frame at the Openings " " "  
 Do Do at other places " " "  
 Keelsons " " "  
 Clamps and Shelves " " "  
 Ceiling " " "  
 Rudder " " "  
 Copper F.Y.M. When put on 1865

Windlass and Capstan Good  
 Pumps "  
 Boats "  
 Masts, Yards, &c. "  
 Sails "  
 Anchors No. of 3 D, 1 S, 2 K  
 Cables "  
 Hawsers and Warps "  
 Standing & Running Rigging "

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways where seen Good

Repaired Yellow metal sheathing.

Is now in good and efficient condition and is in my opinion fit to remain as

Classed  
 Committee's Minute 27 February 18 66  
 Character assigned 14A 1

John Maxwell  
 R. J. Reed

Certificate (if required).

Lloyd's Register  
 Foundation  
 LON 650-0329



I Temply date  
Bathurst date



© 2021

Lloyd's Register  
Foundation