

27298

Change of Owners
REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 945 Survey held at London Date Decr 4th 18 65
 on the S. Monarch Master _____
 Tonnage 1350 Built at London When built 1844
1415
 By whom built Green Owners J. D. Macey
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock in Green's lower & East India docks

Last Survey, No. 26103 Port London Classed 12 A1 in Red
SS. 61. 8 gns 5.64

REPAIRS

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways " " "	Breasthooks and Stenson " " "	Pumps " "
Comings " " "	Transoms, Pointers, and Crutches " " "	Boats " "
Upper Deck Beams & Fastenings " " "	Timbers of the Frame at the openings " " "	Masts, Yards, &c. " "
Lower Deck Beams & Fastenings " " "	Ditto Ditto at other places " " "	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers " " "	Keelsons " " "	Sails " "
Sheerstrakes " " "	Clamps and Shelves " " "	Anchors No. of <u>1 B, 1 S, 1 K</u>
Topsides " " "	Ceiling " " "	Cables " "
Wales " " "	Rudder " " "	Hawsers and Warps " "
Plank (Bottom) and Counter " " "	Copper <u>F. Y. M.</u> When put on <u>1864</u>	Standing & Running Rigging " "

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. where seen Good except deck which is to be caulked

Is now in good and efficient condition fit to carry dry and perishable cargoes to and from all parts of the world and is in our opinion eligible to remain as classed, should the Committee receive the appended guarantee from the Owner.

The Amount of Fee.....£ 1 : — : — is received by me, John Maxwell

Special..... 1 : 1 : 0

Certificate (if required) _____

Committee's Minute 2nd March 18 66
16th

Character assigned See No 27352

LON 650-0339



© 2021

Lloyd's Register Foundation