

27312

S.
 6.
 1856
 1856

REPAIRS

Some extra fastenings have been recently put in the twin deck ceiling planks. —

Decks		Treenails		Windlass and Capstan	
Waterways	in good order //	Breasthooks and Stemson	good //	Pumps	in good order //
Comings	//	Transoms, Pointers, and Crutches	//	Boats	//
Upper Deck Beams & Fastenings	//	Timbers of the Frame at the openings	//	Masts, Yards, &c.	//
Lower Deck Beams & Fastenings	//	Ditto Ditto at other places	//	Condition, how ascertained	//
Planksheers	//	Keelsons	//	Sails	//
Sheerstrakes	//	Clamps and Shelves	//	Anchors No. of 3	//
Topsides	//	Ceiling	//	Cables	//
Wales	//	Rudder efficient	//	Hawsers and Warps	//
Plank (Bottom) and Counter	//	Copper J. M. on felt When put on now	//	Standing & Running Rigging	//
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	good		

I am of opinion She is entitled to remain as Clerk
10. A. S.
Samuel Rogers

Character assigned

Lloyd's Register
Foundation
LH650-0286

Victoria

REPORT of SURVEY for REPAIRS



© 2021

Lloyd's Register
Foundation