

27332

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 945 on the **S "Monarch"** Survey held at **London** Date **Feb 23rd** 18 **66**
Master **Macey**
Tonnage **1350** Built at **London** When built **1844**
By whom built **Green** Owners **C. J. Macey**
Port belonging to **London** Destined Voyage **New Zealand**
If Surveyed Afloat or in Dry Dock **in East India Dock**

Last Survey, No. **27298** Port **London** Classed **12 A1 in Red**
S.S. **61.8 gns** **5.64**

REPAIRS

Anchors now on board as guaranteed by Owner, see letter

Present Condition of the								
Decks	when seen	Good	Treenails	when seen	Good	Windlass and Capstan		Good
Waterways	"	"	Breasthooks and Stemson	"	"	Pumps		"
Comings	"	"	Transoms, Pointers, and Crutches	"	"	Boats		"
Upper Deck Beams & Fastenings	"	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.		Condition, how ascertained from enquiry was seen from deck
Lower Deck Beams & Fastenings	"	"	Ditto Ditto at other places	"	"	Sails		"
Planksheers	"	"	Keelsons	"	"	Anchors No. of	3 B, 1 S, 1 K	
Sheerstrakes	"	"	Clamps and Shelves	"	"	Cables		"
Topsides	"	"	Ceiling	"	"	Hawsers and Warps		"
Wales	"	"	Rudder	"	"	Standing & Running Rigging		"
Plank (Bottom) and Counter	"	"	Copper FLYNT When put on	1864				
General Observations and Opinion,			Caulking of Bottom, Deck, & Waterways.			when seen Good		

Is now in good condition fit to carry dry and perishable cargoes to and from all parts of the world and is in my opinion fit to remain as classed

The Amount of Fee.....£ is received by me, **John Maxwell**
Special..... : :
Certificate (if required) : :

Committee's Minute **16th March** 18 **66**
Character assigned **A 1 in Red**

Monarch
Date



© 2021

Lloyd's Register
Foundation