

REPORT of SURVEY for REPAIRS.

27484

No. in Reg. Book. **No.** 350 Survey held at London Date 14th to 24th May 18 66.
 on the Ship "Lobelia". Master Holman.
 Tonnage 840 Built at Sunderland. When built 1855.
 By whom built _____ Owners J. Lidgett.
 Port belonging to London. Destined Voyage Shanghai.
 If Surveyed Afloat or in Dry Dock Linckhite Dry Dock and East India Dock.

Last Survey, No. 25968 Port London. Classed 13. A. 1
 1.64

REPAIRS

Now done:- Yellow Metal sheathing stripped off the Bottom, - and caulked from steel to the metal. - line. - Resheathed with Yellow metal on felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>Timber</u>	Breasthooks and Stemson	Pumps <u>Two</u>
Comings } <u>Good</u>	Transoms, Pointers, and Crutches	Boats <u>Three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>By inquiry & observation</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3. 15. 2K.</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter <u>faulked.</u>	Copper <u>on felt</u> When put on <u>now.</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	<u>Good where tested.</u>

She is now in good and efficient condition, and fit, in my opinion to remain as fitted.

The Amount of Fee.....£ : : is received by me.

Special..... 1 : 1 : -

Certificate (if required) : :

Committee's Minute 29th May 18 66.

Character assigned 13 A 1



© 2021

Lloyd's Register

Foundation