

Rev. 1.2.66

REPORT of SURVEY for REPAIRS.

No. in 7. Book. **No.** _____ Survey held at London Date Jan 7. 15th 18 66
on the BK "Enthusiast" Master Charles Amy
Tonnage 283 Built at Sunderland When built 1857
By whom built ✓ Owners Doward
Port belonging to Liverpool Destined Voyage Antigua
If Surveyed Afloat or in Dry Dock in West India dock

Last Survey, No. 27532 Port London. Classed 10 A
REPAIRS in consequence of damage, see special report. Cont 7

Renewed one rough tree stanchion of English Oak; repaired main + top gall^{ts} sails & bulwarks; renewed both hawse pipes re-bolted pall bitt; caulked from metal line to waterway with deck from windlass forward.

Present Condition of the

Decks <u>where seen good</u>	Treenails <u>when seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>"</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>Condition, how ascertained, from enquiry & as seen from deck</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Sails <u>"</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>" " "</u>	Cables <u>"</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Hawsers and Warps <u>"</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Standing & Running Rigging <u>"</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>F & Y M</u> When put on <u>1864</u>	
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good condition and is in my opinion fit to remain as classed.

The Amount of Fee.....£ : 10: is received by me, Thos. J. Harwell
Special.....: :
Damage fee £2.2.0 Paid Jan 21
Certificate (if required) : :

Committee's Minute _____ 18 _____
Character assigned _____