

27569

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 376 Survey held at London Date the 28th July 5th 1866
on the "S. Windsor Castle" Master W. Price
Tonnage 1074 Built at Sunderland When built 1857
By whom built _____ Owners Green
Port belonging to London Destined Voyage _____
If Surveyed Afloat or in Dry Dock Green's Upper dock & East India Dock.

Last Survey, No. 26859 Port London Classed 13. A. I.
6.65.

REPAIRS now done:

The Yellow Metal sheathing patched, and the vessel re-caulked from Metal-line to Waterway seams.

Renewed - the Mainmast and the Fore and Main Rigging.

Present Condition of the

Good where seen	Good where seen	Good.
Deck	Treenail	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>by inquiry &c</u>
Planksheers	Keelsons	Sails <u>Sufficient</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	<u>F.Y.M.</u> When put on <u>1865</u>	Standing & Running Rigging

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways.

She appears to be in good and efficient condition, and eligible, in our opinion, to remain as classed - 13. A. I.

The Amount of Fee.....£ — : — : is received by me,

Special..... — : — : —

Certificate (if required) : :

Committee's Minute 10th July 1866.

Character assigned 13 A. I.



Lloyd's Register Foundation

Lon 651-0034