

27011

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 329 Survey held at London Date July 16th 18 66
 on the S. Flower Master _____
 Tonnage 411 Built at Sunderland When built 1858
 By whom built _____ Owners Colonial Co. L^{td}
 Port belonging to London Destined Voyage West Indies
 If Surveyed Afloat or in Dry Dock Bridge Dock

New 24/7/66

Last Survey, No. 27042 Port London Classed 13A1
 REPAIRS 65

a leak found and stopped and the yellow metal repaired.

Present Condition of the

Decks	<i>Good where seen</i>	Treenails	<i>Good where seen</i>	Windlass and Capstan	<i>Good & sufficient</i>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of	
Topsides		Ceiling		Cables	
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper		When put on <u>1865</u>	

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

This vessel is eligible in my opinion to remain classed

The Amount of Fee.....£ : : is received by me, 13A1

Special..... : :

Certificate (if required) : :

Thos M. Wilson

Committee's Minute 24th July 18 66

Character assigned 13A1

MA



© 2019
 Lloyd's Register Foundation
 LON 651 - 00 68