

REPORT of SURVEY for REPAIRS.

27671

Rec 21/8/66

No. in Reg. Book. **No.** 286 on the *S "Telaino"* Survey held at *London* Date *August 20th* 18 *66*
 Master *C.H. Renant*
 Tonnage *702* Built at *Aberdeen* When built *1863*
 By whom built *Hall* Owners *J & D Parker*
 Port belonging to *London* Destined Voyage *New Zealand*
 If Surveyed Afloat or in Dry Dock *in Union & East India Docks*

Last Survey, No. *26257* Port *London* Classed *13.A1*
7.64

REPAIRS

Stripped Yellow metal sheathing caulked from Keel to Planksheer and re-sheathed with Yellow metal over part felt & part paper.

Present Condition of the

| | | |
|-----------------------------------|---|--|
| Decks <i>where seen Good</i> | Treenails <i>where seen Good</i> | Windlass and Capstan <i>Good</i> |
| Waterways | Breasthooks and Stemson | Pumps |
| Comings | Transoms, Pointers, and Crutches | Boats |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Condition, how ascertained <i>from enquiry & as seen from deck</i> |
| Planksheers | Keelsons | Sails |
| Sheerstrakes | Clamps and Shelves | Anchors No. of <i>3 B, 1 S, 2 K</i> |
| Topsides | Ceiling | Cables |
| Wales | Rudder | Hawsers and Warps |
| Plank (Bottom) and Counter | Copper <i>YM pt felt</i> When put on <i>1866</i> | Standing & Running Rigging |
| General Observations and Opinion, | Caulking of Bottom, Deck, & Waterways. <i>where tested Good</i> | |

Is now in good and efficient condition and is in my opinion fit to remain as classed.

The Amount of Fee.....£ : : is received by me.

Special..... 1 : 1 : 0

Certificate (if required) : 5 :

Committee's Minute *26th August* 18 *66*.

Character assigned *13 A1*



© 2019

Lloyd's Register Foundation

Lon 651-0115

Relates

date

REPORT OF SURVEY FOR REPAIRS



© 2019

Lloyd's Register
Foundation