

# REPORT of SURVEY for REPAIRS.

27739

No. in Reg. Book. **No.** 224 Survey held at London Date Aug<sup>18</sup> - Sept<sup>12</sup> 1866.  
 on the Ship Akbar Master J. Pizzey  
 Tonnage 418 Built at Sunderland When built 1851  
 By whom built — Owners Luscombe  
 Port belonging to London Destined Voyage Colombo  
 If Surveyed Afloat or in Dry Dock Carters dry dock & Afloat

Last Survey, No. 26603 Port London Classed Cont<sup>3</sup>/64. 4. A. 1.

## REPAIRS

Stripped off the whole of the Yellow Metal Sheathing  
 Took off the Hawsepipes, Hawse boxes. Cut out two short  
 lengths of defective planks in wake of them, and  
 introduced two of English Oak (Starb. Side) Cut out  
 some worming on the port bow, fitted two new Hawsepipes  
 New Foremast, a New Bowsprit. Refitted and made the rigging  
 all good. Caulked from Keel to Gunwale. Deck seams &  
 Resheathed with Yellow Metal on felt up to 18 ft

## Present Condition of the

Decks <u>in good order</u>	Treenails <u>where seen good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>firm</u>	Timbers of the Frame at the openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto Ditto at other places <u>"</u>	Condition, how ascertained <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3</u> <u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Wales <u>"</u>	Rudder <u>effect</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Gepper <u>1 1/2" on felt</u> When put on <u>now</u>	Standing & Running Rigging <u>"</u>
General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. <u>Good</u>		

I am of opinion this Vessel is entitled to remain as Class'd  
 Cont<sup>3</sup> 4. A. 1.

The Amount of Fee.....£ 2 : — : is received by me  
 Special..... 2 : 2 :  
 Certificate (if required) : 5 : —

Committee's Minute 25 September 1866

Character assigned Cont<sup>3</sup> 4. A. 1.

record repair

mtb



© 2019

Lloyd's Register  
Foundation

LOW 651 - 0168