

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 598 on the 1/2<sup>te</sup> "South Land" Survey held at London Date Sept: 21<sup>st</sup> 1886  
 Tonnage 270 Built at "Peterhead" Master Thom When built 1864 - 3mo  
 By whom built \_\_\_\_\_ Owners J. Ross  
 Port belonging to Leith Destined Voyage Natal  
 If Surveyed Afloat or in Dry Dock Gun Dock

Last Survey, No. 2165 Port Merdeev. Classed 7 A 1  
 REPAIRS 5, 64

*Yellow metal stripped off; recaulked from keel to metal line and the yellow metal sheathing removed on Felt.*

## Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Good</u>	Windlass and Capstan	
Waterways	<u>do</u>	Breasthooks and Stenson	<u>do</u>	Pumps	
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	
Upper Deck Beams & Fastenings	<u>do</u>	Timbers of the Frame at the openings	<u>do</u>	Masts, Yards, &c.	<u>In good order</u>
Lower Deck Beams & Fastenings	<u>do</u>	Ditto Ditto at other places	<u>do</u>	Sails	<u>and</u>
Planksheers	<u>do</u>	Keelsons	<u>do</u>	Anchors No. of	<u>sufficient</u>
Sheerstrakes	<u>do</u>	Clamps and Shelves	<u>do</u>	Cables	
Topsides	<u>do</u>	Ceiling	<u>do</u>	Hawsers and Warps	
Wales	<u>do</u>	Rudder	<u>do</u>	Standing & Running Rigging	
Plank (Bottom) and Counter	<u>do</u>	Copper <u>F. &amp; M.</u> When put on <u>now</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good when tested

*This vessel is eligible in our opinion to remain classed 7 A 1*

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 3  
 Certificate (if required) : 5 : 3

Committee's Minute 5<sup>th</sup> October 1886

Character assigned 7 A 1  
*record 4 M.*  
*WMT*



© 2019

Lloyd's Register Foundation

LON 651 - 0193