

REPORT of SURVEY for REPAIRS.

27779

No. in Reg. Book. **No.** 963 Survey held at London Date Sept 29th 18 66
 on the S^e Countess of Carrick Master J. Gibson
 Tonnage 99 Built at Ardrossan When built 1864 - 3 mo
 By whom built _____ Owners M^c Kenna
 Port belonging to Girvan Destined Voyage Bayonne
 If Surveyed Afloat or in Dry Dock Bull head dock

Last Survey, No. 4758 Port Glasgow Classed 7 A 1
4.64

REPAIRS

In consequence of damage, in way of port main rigging, three toptimbers new of English Oak, two wale planks of Baltic oak, seven planks of ceiling and one length of clamp of Red pine — Reaulted in way of the damage.

Present Condition of the

Decks	} <u>Good</u>	Treenails	} <u>Good</u>	Windlass and Capstan	} <u>Good and sufficient</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper When put on			

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

This vessel is eligible in my opinion to remain classed 7 A 1

The Amount of Fee.....£ : 10 : — is received by me,

Special..... : 10 : 6

Certificate (if required) _____

Committee's Minute 9th October 18 66

Character assigned 7 A 1

record damage upon
 WH

Thos. W. Hawn
 R. J. Reed.



© 2019

Lloyd's Register Foundation

LON 651-0198