


REPORT of SURVEY for REPAIRS.

27790

No. in Reg. Book. **No.** 928 on the Bg. "Corporation"  Master Watkins
 Survey held at London Date October 3rd to 5th 18 86
 Tonnage 123 Built at Grimsby When built 1854
 By whom built G Owners Foster & Co.
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Globe Dock

Last Survey, No. 26043 Port London Classed 12. A. I.
 S. L. S.

REPAIRS now done.

Channels removed, and the chain plates fitted to side; the false keel re-fitted and fastened, and the mudlows turned out and examined; recaulked from metal-line to Waterway seams.

Present Condition of the

Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame at the openings <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Ditto Ditto at other places <u>do</u>	Condition, how ascertained <u>by engine & as seen.</u>
Planksheers <u>do</u>	Keelsons <u>do</u>	Sails <u>Sufficient</u>
Sheerstrakes <u>do</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do</u>
Topsides <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Wales <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Plank (Bottom) and Counter <u>do</u>	Copper <u>F. J. M.</u> When put on <u>1865</u>	Standing & Running Rigging <u>do refitted.</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where seen

Is now in good and efficient condition and eligible, in my opinion, to remain classed — 12. A. I.

The Amount of Fee.....£ — : — is received by me,

Special..... — : — : —

Certificate (if required) : :

Committee's Minute 9th October 18 86

Character assigned 12 A. I.



© 2019

Lloyd's Register
Foundation

LON 651-0206