

27802

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 350 Survey held at London Date Oct 10th 18 66
on the "Sea Star" Master Jas H. Vanev
Tonnage 590 Built at Aberdeen When built 1855
By whom built 654 Hall Owners J. Hutchinson
Port belonging to London Destined Voyage Adelaide
If Surveyed Afloat or in Dry Dock in Union & London Docks

Last Survey, No. 8413 Port Sunderland Classed 9 A1
REPAIRS in consequence of damage see special report. Cont 64 3 5.65

Stripped Yellow metal sheathing, caulked from keel to waterway seams with three seams of deck on each side and re-sheathed with Yellow metal over felt.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " "</u>	Breasthooks and Stemson <u>" " "</u>	Pumps <u>"</u>
Comings <u>" " "</u>	Transoms, Pointers, and Crutches <u>" " "</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>" " "</u>	Timbers of the Frame at the openings <u>" " "</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>" " "</u>	Ditto Ditto at other places <u>" " "</u>	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers <u>" " "</u>	Keelsons <u>" " "</u>	Sails <u>"</u>
Sheerstrakes <u>" " "</u>	Clamps and Shelves <u>" " "</u>	Anchors No. of <u>3 B, 1 S, 1 K</u>
Topsides <u>" " "</u>	Ceiling <u>" " "</u>	Cables <u>"</u>
Wales <u>" " "</u>	Rudder <u>" " "</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>" " "</u>	Copper <u>F.Y.M.</u> When put on <u>1866</u>	Standing & Running Rigging <u>"</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good and efficient condition and is in my opinion fit to remain as classed.

The Amount of Fee.....£ 2 : 2 : 0 is received by me, Thos Maxwell
Special..... 1 : 1 : 0
Certificate (if required) : 5 :

Committee's Minute 16 October 18 66

Character assigned Cont 3 A 1
record