

27810

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 953 Survey held at London Date August 30th to 31st 18 66.
on the "S. Costa Rica Packet" Master Le Lacheur
Tonnage 531 Built at Guernsey When built 1861
By whom built _____ Owners Le Lacheur
Port belonging to Guernsey Destined Voyage _____
If Surveyed Afloat or in Dry Dock Nelson Dry Dock.

Last Survey, No. 26984 Port London Classed 15. A. I.
REPAIRS now done: P. 65.

The Yellow Metal sheathing stripped, the vessel re-caulked from keel to Metalline, and resheathed with Yellow Metal over ~~Le~~ Paper.

Present Condition of the		
Decks <u>Good where seen</u>	Treenails <u>Good where seen</u>	Windlass and Capstan <u>Good</u>
Waterways //	Breasthooks and Stenson //	Pumps //
Comings //	Transoms, Pointers, and Crutches //	Boats //
Upper Deck Beams & Fastenings //	Timbers of the Frame at the openings //	Masts, Yards, &c. //
Lower Deck Beams & Fastenings //	Ditto Ditto at other places //	Condition, how ascertained <u>by inquiry & inspection</u>
Planksheers //	Keelsons //	Sails <u>Sufficient</u>
Sheerstrakes //	Clamps and Shelves //	Anchors No. of <u>do</u>
Topsides //	Ceiling //	Cables <u>do</u>
Wales //	Rudder //	Hawsers and Warps <u>do</u>
Plank (Bottom) and Counter //	<u>P. Y. M.</u> When put on <u>Now</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. Good where tested.

The appears to be in good and efficient condition, and eligible, in my opinion, to remain as classed - 15. A. I.

R. J. Reed.

The Amount of Fee.....£ : : is received by me,

Special..... 1 : 1 : 0 ago

Certificate (if required) : :

Committee's Minute 19th October 18 66

Character assigned 15th 1



© 2019

Lloyd's Register Foundation

LON 651-0224