

# ANNUAL SURVEYS.

27895  
Dec 22/11/66

No. 748 Survey held at London Date Nov. 3<sup>rd</sup> to 20<sup>th</sup> 1866.  
 on the Ship "Medway" Master J. Grieres  
 Tonnage 612 Built at Scarboro When built 1845  
 By whom built Lindall Owners J. Marshall  
 Port belonging to London Destined Voyage Colombo  
 If Surveyed Afloat or in Dry Dock Pontons Victoria Docks, and Victoria Docks

Last Survey, No. 2619 Port of London Classed 12.A.1 (Dist 64.8 pps)  
64 (6.64.)

<p>The present Condition of the</p> <p>Decks _____</p> <p>Waterways _____</p> <p>Comings _____</p> <p>Upper Deck Beams &amp; Fastenings _____</p> <p>Lower Deck Beams &amp; Fastenings _____</p> <p>Planksheers _____</p> <p>Sheerstrakes _____</p> <p>Topsides <u>caulked</u></p> <p>Wales _____</p> <p>Plank (Bottom) and Counter _____</p>	<p>Treenails _____</p> <p>Breasthooks and Stemson _____</p> <p>Transoms, Pointers, and Crutches _____</p> <p>Timbers of the Frame at the Openings _____</p> <p>Ditto ditto at other places _____</p> <p>Keelsons _____</p> <p>Clamps and Shelves _____</p> <p>Ceiling _____</p> <p>Rudder <u>Good</u></p> <p>Copper <u>and Y.M.</u> When put on <u>1864.</u></p>	<p>Windlass and Capstan _____</p> <p>Pumps <u>four</u></p> <p>Boats <u>three</u></p> <p>Masts, Yards, &amp;c. <u>Good</u></p> <p>Sails _____</p> <p>Anchors No. of <u>3 B. 1 S. 2 K.</u></p> <p>Cables _____</p> <p>Hawsers and Warps _____</p> <p>Standing &amp; Running Rigging _____</p>
---	--	---

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways Good where seen

*Sighted bottom, the yellow metal patched, hold much lumbered with ballast &c. caulked the topsides; as far could be seen, she is now in good and efficient condition and fit in our opinion to remain as classed. A. 1.*

Committee's Minute 23<sup>rd</sup> November 1866 Joseph. Kew.  
 Character assigned Rest. SA 1 M.D. H. J. Cornish  
Certificate (if required)

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_ 18\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Classed \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_

<p>The present Condition of the</p> <p>Decks _____</p> <p>Waterways _____</p> <p>Comings _____</p> <p>Upper Deck Beams &amp; Fastenings _____</p> <p>Lower Deck Beams &amp; Fastenings _____</p> <p>Planksheers _____</p> <p>Sheerstrakes _____</p> <p>Topsides _____</p> <p>Wales _____</p> <p>Plank (Bottom) and Counter _____</p>	<p>Treenails _____</p> <p>Breasthooks and Stemson _____</p> <p>Transoms, Pointers, and Crutches _____</p> <p>Timbers of the Frame at the Openings _____</p> <p>Ditto ditto at other places _____</p> <p>Keelsons _____</p> <p>Clamps and Shelves _____</p> <p>Ceiling _____</p> <p>Rudder _____</p> <p>Copper _____ When put on _____</p>	<p>Windlass and Capstan _____</p> <p>Pumps _____</p> <p>Boats _____</p> <p>Masts, Yards, &amp;c. _____</p> <p>Sails _____</p> <p>Anchors No. of _____</p> <p>Cables _____</p> <p>Hawsers and Warps _____</p> <p>Standing &amp; Running Rigging _____</p>
--	---	--

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_  
 Character assigned \_\_\_\_\_

