

REPORT of SURVEY for REPAIRS.

28070

No. in Reg. Book. **No.** 312 Survey held at London Date Feb^y 11th to 14th 1867.
 on the Bk "Duke of Wellington" Master J. Bolton
 Tonnage 487 Built at Dumbarton When built 1842.
 By whom built _____ Owners M^r Lee and Co.
 Port belonging to Arrossan Destined Voyage Clyde, and West Indies
 If Surveyed Afloat or in Dry Dock King and Queen dry Dock and West India D^{ocks}
 Last Survey, No. 2205 Port Glasgow. Classed 10 Red A. 1. (7.64.)
 REPAIRS Now done. 5564-7

Lighted bottom, renewed one length of false keel forward, with Riga fir, and two pintles to Rudder with yellow metal, and fastened with copper bolts; patched the yellow metal on bottom, and stem &c., payed the whole with two coats of Peacock's patent paint.
 Hold much lumbered with ballast and dunnage.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>Two</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>Three</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>inspⁿ and enquiry</u>
Planksheers	Keelsons <u>part seen</u>	Sails <u>where</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 15. 11.</u>
Topsides	Ceiling <u>part seen</u>	Cables <u>seen</u>
Wales	Rudder pintles <u>part new</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>and Y.M.</u> When put on <u>1864</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	<u>Good when seen.</u>

She is now in good and efficient condition and fit in my opinion to remain as Classed. Viz. Red A. 1.
 Joseph Keen.

The Amount of Fee.....£ : : is received by me,

Special...../ 1 : 0

Certificate (if required) : 5 : :

Committee's Minute 19th February 1867
 Character assigned End 1 in red M.A.S.



© 2019

Lloyd's Register Foundation

LOW 051 - 0438