

REPORT of SURVEY for REPAIRS.

28189

No. in Reg. Book. **No.** 531 Survey held at London Date 4th to 6th April 1864
 on the Ship "Gingala" Master E. W. Neilson
 Tonnage 799 Built at Workington When built 1865 (i. m. o.)
 By whom built Lampport Owners W. Nicol
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Messrs Wigram's Dry Dock.

Last Survey, No. 2227 Port Whitehaven Classed 14 A 1
 2/65

REPAIRS

Now done:- The Yellow Metal sheathing stripped off the Bottom, and the Vessel caulked from the Keel to the Planksheers.
 Resheathed the Bottom with Yellow Metal on Whitings best hair-felt.

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways	} <u>Good</u>	Breasthooks and Stemson	} <u>Good</u>	Pumps <u>Two</u>	} <u>Good where seen</u>
Comings		Transoms, Pointers, and Crutches		Boats <u>3 H^o</u>	
Upper Deck Beams & Fastenings	} <u>where</u>	Timbers of the Frame at the openings	} <u>where</u>	Masts, Yards, &c.	} <u>By inquiry and observation</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers	} <u>where</u>	Keelsons	} <u>where</u>	Sails	} <u>Good and</u>
Sheerstrakes		Clamps and Shelves		Anchors No. of <u>3 B. 15. 2 K</u>	
Topsides	} <u>faulked</u>	Ceiling	} <u>seen</u>	Cables	} <u>sufficient</u>
Wales		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter	} <u>faulked</u>	Copper <u>H. Y. M.</u> When put on <u>now</u>	} <u>where seen</u>	Standing & Running Rigging	} <u>where seen</u>
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<u>Good where tested.</u>	

She is in good and efficient condition, and fit, in our opinion, to remain classed: A. 1.

The Amount of Fee.....£ — : — : is received by me.

Special..... 1 : 1 : }

Certificate (if required) : 5 : }

Committee's Minute 12th April 18 64

Character assigned 14 A 1

record YM M.S.



© 2019

Lloyd's Register Foundation

LOW 651-D 526