

Declined 28191

REPORT of SURVEY for ~~REPAIRS~~.

No. in Reg. Book. **No.** 37 Survey held at London Date April 5th 1867
 on the Brig "Valhot" Master _____
 Tonnage 250 Built at Southampton When built 1851
 By whom built _____ Owners Newman
 Port belonging to London Destined Voyage _____
 If ~~Surveyed~~ Afloat or in Dry Dock Upper Globe dry Dock

Nov 10/4/67

Last Survey, No. 24759 Port London Classed 13 — (7.62.)

REPAIRS

The Captⁿ declined putting the Ship under Survey.
 Joseph Keen.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper When put on	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways.	

The Amount of Fee.....£ : : is received by me.

Special..... : :

Certificate (if required) : :

Committee's Minute 12th April 1867

Character assigned Defered W.S.



© 2019

Lloyd's Register Foundation

LON 657 - 0 528