

28216

REPORT of SURVEY for REPAIRS.

Nov 28/12/65

No. in Reg. Book. **No.** Survey held at London Date Decr^r 19th - 26th 1865.
on the Ship Janet Ferguson Master Jno^r Sawyer.
Tonnage 581 Built at Glasgow When built 1864.
By whom built Stephen Owners Bain Bros
Port belonging to Glasgow Destined Voyage _____
If Surveyed Afloat or in Dry Dock "Nelson"

Last Survey, No. 28215 Port London Classified 14. A. 1.
previous reports.

REPAIRS

from collision. New Cutwater, Head Yails, and all in connection made complete, Six iron ribs on the Port bow, at the upper part, cut out, and made good, with double revers'd angle irons, and the planking inside and outside the forecastle, on the same side, renew'd; and made efficient as before. Sighted and repaired the Yellow Metal.

Present Condition of the

Decks	<i>in good order</i>	Treenails	<i>good</i>	Windlass and Capstan	<i>in good order</i>
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	<i>firm</i>	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	<i>from the deck</i>
Planksheers	"	Keelsons	"	Sails	"
Sheerstrakes	"	Clamps and Shelves	"	Anchors No. of <i>3</i>	"
Topsides	"	Ceiling	"	Cables	"
Wales	"	Rudder	<i>efficient</i>	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper	<i>Yel^u Metal on felt</i>	Standing & Running Rigging	"
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.		<i>good</i>	

I am of opinion this Vessel is entitled to remain as Class'd 14. A. 1. Excp^d B. S. -

The Amount of Fee.....£ *2* : — : } is received by me,
Special..... *2* : *2* : }
Certificate (if required) — : — : }

Samuel Pearson

Committee's Minute _____ 18_____
Character assigned _____

James Ferguson

REPORT OF SURVEY FOR REPAIRS



© 2019

Lloyd's Register
Foundation