

28244

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 276 Survey held at London Date April 30th 18 67
 on the 43rd + Cavalier Master Rao
 Tonnage 355 Built at Southwick When built 1864
 By whom built _____ Owners Howard & Deben
 Port belonging to Liverpool Destined Voyage Swansea & West Coast
 If Surveyed Afloat or in Dry Dock gun dry dock

Last Survey, No. 2457 Port Glasgow Classed 12 A 1
 REPAIRS 3.66

Yellow metal stripped off, recaulked from keel to metal line and the yellow metal sheathing renewed on Felt.

Present Condition of the	
Decks	Treenails
Waterways	Breasthooks and Stemson
Comings	Transoms, Pointers, and Crutches
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings
Lower Deck Beams & Fastenings	Ditto Ditto at other places
Planksheers	Keelsons
Sheerstrakes	Clamps and Shelves
Topsides	Ceiling
Wales	Rudder
Plank (Bottom) and Counter	Copper <u>T. & T. N.</u> When put on <u>new</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>
	Windlass and Capstan
	Pumps
	Boats
	Masts, Yards, &c.
	Condition, how ascertained
	Sails
	Anchors No. of
	Cables
	Hawsers and Warps
	Standing & Running Rigging

This vessel is now in a good and efficient state of repair, and is eligible, in my opinion, to remain classed

The Amount of Fee.....£ : : is received by me.

Special..... 1 : 1 : 3

Certificate (if required) : 5 : 3

Committee's Minute 7th May 18 67

Character assigned 12 A 1

Thos. W. Wawn

Joseph T. Wawn
 Lloyd's Register Foundation