

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 95 on the BK "Harmony" Survey held at London Date May 14th 18 67
 Tonnage 251 Built at Ly. Yarmouth Master H. Linklater When built 1861
 By whom built Tellowes Owners Badham
 Port belonging to London Destined Voyage Labrador
 If Surveyed Afloat or in Dry Dock in Bridge Dock and West India Dock

Last Survey, No. 2684D Port London Classed 13 A1
5.65

REPAIRS

c.f

Stripped Zinc sheathing; caulked from keel to metal line and re-sheathed with Yellow metal over felt.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>" " " "</u>	Breasthooks and Stemson <u>" " " "</u>	Brown & Hanfield's patent iron Pumps <u>" "</u>
Comings <u>" " " "</u>	Transoms, Pointers, and Crutches <u>" " " "</u>	Boats <u>" "</u>
Upper Deck Beams & Fastenings <u>" " " "</u>	Timbers of the Frame at the openings <u>" " " "</u>	Masts, Yards, &c. <u>" "</u>
Lower Deck Beams & Fastenings <u>" " " "</u>	Ditto Ditto at other places <u>" " " "</u>	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers <u>" " " "</u>	Keelsons <u>" " " "</u>	Sails <u>" "</u>
Sheerstrakes <u>" " " "</u>	Clamps and Shelves <u>" " " "</u>	Anchors No. of <u>9 B, 1 S, 2 K</u>
Topsides <u>" " " "</u>	Ceiling <u>" " " "</u>	Cables <u>" "</u>
Wales <u>" " " "</u>	Rudder <u>" " " "</u>	Hawsers and Warps <u>" "</u>
Plank (Bottom) and Counter <u>" " " "</u>	Copper <u>F.Y.M.</u> When put on <u>1864</u>	Standing & Running Rigging <u>" "</u>
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested Good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ : — : is received by me. John Maxwell

Special..... / : / : 0

Certificate (if required) : : :

Committee's Minute 21st May 18 67

Character assigned 13 A1



© 2021

Lloyd's Register Foundation

LON652-0045

Hammer



© 2021

Lloyd's Register
Foundation