

ANNUAL SURVEYS.

2837

No. 453 Survey held at London Date 12th June 1864
 on the Barque "Prince of Wales" Master Robert Adamson
 Tonnage 509 Built at Southampton When built 1850
 By whom built _____ Owners Hudson's Bay Company
 Port belonging to London Destined Voyage Vancouver's Island
 If Surveyed Afloat or in Dry Dock Higraus Dry dock and West India dock

Last Survey, No. 8694 Port of Sunderland Classed 13. A. 1. 1
Port 63 for 9 yrs. 3.66

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2 No.</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>3 No.</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of <u>3 B. 15. 2 K.</u>
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper <u>11 1/4 in.</u> When put on <u>1866</u>	

General Observations and Opinion, Caulking of Bottom, Deck, and Waterways
The Yellow metal sheathing patched. She is
in good and efficient condition, and fit, in my opinion, to
rejoin classed: A. 1.

Committee's Minute 21st June 1864
 Character assigned Port 9
W. Williamson
 Certificate (if required)

No. _____ Survey held at _____ Date _____ 18____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the Openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto ditto at other places	Sails
Planksheers	Keelsons	Anchors No. of
Sheerstrakes	Clamps and Shelves	Cables
Topsides	Ceiling	Hawsers and Warps
Wales	Rudder	Standing & Running Rigging
Plank (Bottom) and Counter	Copper _____ When put on _____	

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18____

Character assigned _____



© 2021

Lloyd's Register Foundation

Lon652-0117