

28378

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 235 Survey held at London Date May 18th to June 10th 1864
 on the Ship "Nourmahal" Master J. Fowler
 Tonnage 241 Built at Bridgeport When built 1856
 By whom built _____ Owners Prowse and Co
 Port belonging to Liverpool Destined Voyage Lidney
 If Surveyed Afloat or in Dry Dock Princes dry dock, and London Docks.

Last Survey, No. 26963 Port London Classed B.S.A.1 (7.65)
 REPAIRS Now done

The Yellow Metal Sheathing stripped; Caulked from Keel to planksheers, including Stanchions, and two seams of Deck, and resheathed the bottom with Yellow Metal on Felt.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>4</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>inspⁿ and engulⁿ</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2 K</u>
Topsides	Ceiling	Cables
Wales	Rudder <u>HA good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper and <u>Y.M.</u> When put on <u>now</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>	

She is now in good and efficient condition, and fit in our opinion to remain as Classed Viz A.1.
Joseph Keen.

The Amount of Fee.....£ — : — : is received by me

Special...../— /— 0 } Agd

Certificate (if required) : 5 : }

Committee's Minute 25th June 18 64

Character assigned 13/1

record



©2021

Lloyd's Register Foundation

LON 652-0124