

28383

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 87 Survey held at London Date 14th June 18 67
on the Ship "Kent" Master H. G. Holt
Tonnage 927 Built at London When built 1853
By whom built _____ Owners Digrams
Port belonging to London Destined Voyage Melbourne
If Surveyed Afloat or in Dry Dock Digrams' dry dock and East India dock.

Last Survey, No. 27772 Port Lon. Classed 13. A. 1. font: 66, for 4 yrs. 19.66.

REPAIRS

Now done:-

The Yellow metal sheathing stripped off the Bottom, and faulted from Keel to metal-line. Resheathed the Bottom with yellow metal on felt.

Present Condition of the

| Decks | Treenails | Windlass and Capstan |
|-----------------------------------|---|--|
| Waterways | Breasthooks and Stemson | Pumps <u>2 H.</u> |
| Comings | Transoms, Pointers, and Crutches | Boats <u>4 H.</u> |
| Upper Deck Beams & Fastenings | Timbers of the Frame at the openings | Masts, Yards, &c. |
| Lower Deck Beams & Fastenings | Ditto Ditto at other places | Condition, how ascertained <u>By Inquiry & observation</u> |
| Planksheers | Keelsons | Sails |
| Sheerstrakes | Clamps and Shelves | Anchors No. of <u>3 B. 15. 2 K.</u> |
| Topsides | Ceiling | Cables |
| Wales | Rudder | Hawsers and Warps |
| Plank (Bottom) and Counter | Copper <u>18 yd.</u> When put on <u>now</u> | Standing & Running Rigging |
| General Observations and Opinion, | Caulking of Bottom, Deck, & Waterways. | |

She is in good and efficient condition, and fit, in my opinion, to remain classed: - A. 1.

The Amount of Fee.....£ — : — : is received by me,

Special..... 1 : 1 :

Certificate (if required) : :

Committee's Minute 25th June 18 67

Character assigned Cont. H. 1



© 2021

Lloyd's Register Foundation

Lon 652-0126