

REPORT of SURVEY for REPAIRS.

28407

No. in Reg. Book. **No.** 169 Survey held at London Date 28th June 18 67
 on the Ship "Renown" Master John H. Taylor
 Tonnage 1293 Built at London When built 1860 (S. Mo.)
 By whom built Green Owners R. & N. Green
 Port belonging to London Destined Voyage Madras
 If Surveyed Afloat or in Dry Dock Green's upper dock and East India dock

Last Survey, No. 27612 Port London Classed 13 A 1
 7.66-

REPAIRS

Now done:- The Bottom sighted and the Yellow metal sheathing patched -
 Caulked the Butts of Topsides, and Sides, the flat of Poop-deck, three seams of the upper deck, on each side, next the Waterway and the Butts of the said deck -
 Renewed the Foremast and Bowsprit of Oregon-pine, and the Fore-topmast, with Red-pine -

Present Condition of the

Decks Partly caulked

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

General Observations and Opinion,

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper F. W. M. When put on 1866

Caulking of Bottom, Deck, & Waterways.

Windlass and Capstan

Pumps 2 H.

Boats 6 H.

Masts, Yards, &c.

Condition, how ascertained Enquired of Carpenter

Sails

Anchors No. of 3 H. 15. 2 H.

Cables

Hawsers and Warps

Standing & Running Rigging

Good where seen

She is in good and efficient condition, and fit, in my opinion, to remain classed: A. 1.

The Amount of Fee.....£ : : is received by me,

Special.....

Certificate (if required) : :

Committee's Minute 2nd July 18 67

Character assigned 13 A 1



© 2021

Lloyd's Register
 FOUNDATION