

28417

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 372 on the Ship **Ship "Winchester"** Survey held at **London** Date **28th June** 18 **67**
Master **John Davison**
Tonnage **1157** Built at **Gimderland** When built **1862 (9. Mo.)**
By whom built **Marshall** Owners **J. Marshall**
Port belonging to **London** Destined Voyage **Calcutta**
If Surveyed Afloat or in Dry Dock **Green's Upper dock and East India dock.**

Last Survey, No. **27453** Port **Lon.** Classed **13. A. 1.**
REPAIRS **Now done:-** 5.66-

The Yellow metal sheathing stripped off the Bottom, and the vessel caulked from Keel to the metal line. - Resheathed the Bottom with yellow metal over felt. -

Present Condition of the

Decks		Treenails		Windlass and Capstan	
Waterways		Breasthooks and Stenson		Pumps 2nd	
Comings	Good	Transoms, Pointers, and Crutches	Good	Boats 5th	Good where seen
Upper Deck Beams & Fastenings		Timbers of the Frame at the opening		Masts, Yards, &c.	
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where	Condition, how ascertained By inquiry of Mate.	
Planksheers		Keelsons		Sails	
Sheerstrakes		Clamps and Shelves		Anchors No. of 3 B. 15. 2 K.	Good
Topsides		Ceiling	seen	Cables	and
Wales	seen	Rudder		Hawsers and Warps	
Plank (Bottom) and Counter		Copper the 4th of When put on now		Standing & Running Rigging	sufficient
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways.	Good where tested		

She is in good and efficient condition, and fit, in my opinion, to remain classed. **A. 1.**

The Amount of Fee.....£ — : — : } is received by me,
Special..... 1 : 1 : }
Certificate (if required) : : }

J. Williamson

Committee's Minute **5th July** 18 **67**

Character assigned **13 A 1**
account J.M.

