

REPORT of SURVEY for REPAIRS.

28520

No. in Reg. Book. **No.** 394 Survey held at London Date August 9th 18 67
 on the 8 " Holmsdale Master Tickell
 Tonnage 1257 Built at Sunderland When built 1858
 By whom built ✓ Owners W. Phillipps & Co
 Port belonging to London Destined Voyage Port Philip
 If Surveyed Afloat or in Dry Dock in Green's lower & East India Docks

Last Survey, No. 27776 Port London Classed 13 A1
 c.f.

REPAIRS

Stripped Yellow metal sheathing, caulked from keel to metal line and re-sheathed with Yellow metal over felt; also hung in shores.

Present Condition of the

Decks <u>where seen Good</u>	Treenails <u>where seen Good</u>	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>from enquiry & as seen from deck</u>
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B, 1 S, 2 K</u>
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>F.Y.M.</u> When put on <u>1867</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>where tested good</u>	

Is now in good and efficient condition and in my opinion eligible to remain as classed.

The Amount of Fee.....£ — : — : is received by me.

Special..... 1 : 1 : 0

Certificate (if required) : : :

Committee's Minute 23rd August 18 67

Character assigned 13

Record Y.M. M.A.S.



© 2021

Lloyd's Register Foundation

LON652-0239

H. D. Medall

REPORT OF THE COMMITTEE ON THE REVENUE

1891-1892



© 2021

Lloyd's Register
Foundation