

28576

REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 311 Survey held at London Date Aug 22nd to 31st 1867
on the Ship "Sea Breeze" Master J. Harry
Tonnage 685 Built at Sunderland When built 1856
By whom built _____ Owners Blyths & Green
Port belonging to London Destined Voyage Mauritius
If Surveyed Afloat or in Dry Dock Bridge (Dry Dock & West Ind. Dock)

Last Survey, No. 27438 Port London Classed 13 A.1.

REPAIRS now done, The Yellow Metal stripped, caulked from keel to gunwale and the bottom resheathed with Yellow Metal on felt - the strake of deck next the waterway on both sides renewed with Yellow Pine - and the midship piece of the rough-tree rail on Starboard side new of Am. Elm -

Present Condition of the

Decks	} good	Treenails	} good	Windlass and Capstan	} good
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>four</u>	
Upper Deck Beams & Fastenings	} where	Timbers of the Frame at the openings	} where	Masts, Yards, &c.	} where
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained	
Planksheers <u>caulked</u>	} seen	Keelsons	} seen	Sails	} seen
Sheerstrakes <u>dr</u>		Clamps and Shelves		Anchors No. of <u>3 BISM</u>	
Topsides <u>dr</u>		Ceiling		Cables	
Wales <u>dr</u>		Rudder		Hawsers and Warps	
Plank (Bottom) and Counter <u>caulked</u>		Copper <u>FLYM</u> When put on <u>now</u>		Standing & Running Rigging	
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>good where tested</u>			

She is now in good condition, fit in our opinion to remain as classed 13 A.1.

The Amount of Fee.....£ - : : is received by me,

Special..... / : / :

Certificate (if required) : : :

Committee's Minute 6th September 1867

Character assigned 13 A.1
read Y. M. C. M. S.



© 2021

Lloyd's Register Foundation