

28658

# Annual REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 287 Survey held at London Date Aug 23<sup>rd</sup> to Sep 24<sup>th</sup> 1867.  
 on the Ship "Power Castle" Master R K Deacow  
 Tonnage 1002 Built at Sunderland When built 1858  
 By whom built \_\_\_\_\_ Owners R Green  
 Port belonging to London Destined Voyage Melbourne  
 If Surveyed Afloat or in Dry Dock Green Up<sup>r</sup> dry S<sup>th</sup> and East India S<sup>th</sup>

Last Survey, No. 27910 Port London Classed B. A. 1. (11.66.)  
 REPAIRS None done.

Lighted bottom, the Yellow Metal patched,  
 Added a Steam Anchor weighing 13 Cwt. the  
 Hold much lumbered.

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps <u>2</u>
Comings	Transoms, Pointers, and Crutches	Boats <u>7</u>
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained <u>ins<sup>pn</sup> and en<sup>g</sup></u>
Planksheers	Keelsons <u>part seen</u>	Sails
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B. 1 S. 2</u>
Topsides	Ceiling <u>part seen</u>	Cables
Wales	Rudder <u>good</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper and Y. M. When put on <u>1866.</u>	Standing & Running Rigging
General Observations and Opinion,	Caulking of Bottom, Deck, & Waterways. <u>Good where seen.</u>	

She is now in good and efficient condition, and  
 fit in my opinion to remain Classed A. 1.

The Amount of Fee.....£ : : is received by me,

Special...../ - / - 0

Certificate (if required) : 5- :

Committee's Minute 4<sup>th</sup> October 1867

Character assigned B A 1



© 2021

Lloyd's Register  
Foundation

Lon 652-0340