

# ANNUAL SURVEYS.

28696

Recd 14.10.67

No. 25 } Survey held at London Date Oct 10 & 11 1867  
 the Bk. "Flying Fish" Master G. Taylor  
 Tonnage 393 Built at Sunderland When built 1858  
 By whom built \_\_\_\_\_ Owners Javan Bros.  
 Port belonging to London Destined Voyage Barbados  
 If Surveyed Afloat or in Dry Dock Bridge Dry Dock

Last Survey, No. 26975 Port of London Classed 13 A.1  
 8.65

The present Condition of the

Decks	<u>good</u> <u>where</u> <u>seen</u>	Treenails	<u>good</u> <u>where</u> <u>seen</u>	Windlass and Capstan	<u>good</u> <u>where</u> <u>seen</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats <u>three</u>	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of <u>3 BISM</u>	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper <u>T &amp; C</u> When put on <u>1865</u>			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

good where seen

now done, the bottom sighted and the Copper patched & the fore and main hatch comings renewed -  
She is now where seen in good and efficient condition fit in my opinion to remain as classed. 13 A.1.

Committee's Minute 15<sup>th</sup> October 1867

Character assigned 13 A.1 M.S.

Certificate (if required)

The Windlass was unhung & stripped in August 1863 and the middle line and peaks cleared and examined in July 1864 - S.H.

18 Defend

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date \_\_\_\_\_  
 on the \_\_\_\_\_ Master \_\_\_\_\_  
 Tonnage \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_

The present Condition of the

Decks	<u>good</u> <u>where</u> <u>seen</u>	Treenails	<u>good</u> <u>where</u> <u>seen</u>	Windlass and Capstan	<u>good</u> <u>where</u> <u>seen</u>
Waterways		Breasthooks and Stemson		Pumps	
Comings		Transoms, Pointers, and Crutches		Boats	
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Masts, Yards, &c.	
Lower Deck Beams & Fastenings		Ditto ditto at other places		Sails	
Planksheers		Keelsons		Anchors No. of	
Sheerstrakes		Clamps and Shelves		Cables	
Topsides		Ceiling		Hawsers and Warps	
Wales		Rudder		Standing & Running Rigging	
Plank (Bottom) and Counter		Copper _____ When put on _____			

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways

Committee's Minute \_\_\_\_\_ 18

Character assigned \_\_\_\_\_



© 2021

Lloyd's Register  
 Certificate (if required).

LON652-0372