

# REPORT of SURVEY for REPAIRS.

28730

No. in Reg. Book. **No.** 300 Survey held at London Date Oct 1<sup>st</sup> to 21<sup>st</sup> 18 67  
 on the Ship "Her Majesty" Master Seymour  
 Tonnage 1112 Built at Calcutta When built 1856  
 By whom built \_\_\_\_\_ Owners Sanderson & Co.  
 Port belonging to London Destined Voyage Bombay  
 If Surveyed Afloat or in Dry Dock Union Dry Dock & East India Dock

Last Survey, No. 19526 Port Liverpool Classed 12A.1

REPAIRS now done, The yellow metal stripped, caulked from sheathing to top of wales, the upper deck, the keel seam of the sheathing, and a listing cut at the hood ends, and the hood ends, caulked - Leak earlings chased in between the beams under the waterway seam on each side and the bottom resheathed with yellow metal

## Present Condition of the

Decks <u>caulked</u>	Treenails	Windlass and Capstan
Waterways <u>"</u>	Breasthooks and Stemson	Pumps
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>good</u>	Boats <u>Sia</u> <u>good</u>
Upper Deck Beams & Fastenings <u>good</u>	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings <u>good</u>	Ditto Ditto at other places	Condition, how ascertained <u>by inspection</u>
Planksheers <u>where</u>	Keelsons <u>where</u>	Sails <u>where</u>
Sheerstrakes	Clamps and Shelves	Anchors No. of <u>3 B 1 S 2 K</u>
Topsides	Ceiling	Cables <u>seen</u>
Wales <u>caulked</u> <u>seen</u>	Rudder <u>seen</u>	Hawsers and Warps
Plank (Bottom) and Counter	Copper <u>YM</u> When put on <u>now</u>	Standing & Running Rigging

General Observations and Opinion, Caulking of Bottom, Deck, & Waterways. good where seen

She is now in good condition fit in my opinion to remain as classed 12A.1.

The Amount of Fee.....£ : : is received by me,

24/00 Special..... : :

Certificate (if required) : :

Committee's Minute 29<sup>th</sup> October 18 67

Character assigned 12A.1 M.S.



© 2021

Lloyd's Register Foundation

LON652-0401