

Composite.

# REPORT of SURVEY for REPAIRS.

No. in Reg. Book. **No.** 350 Survey held at London Date Oct<sup>r</sup> 17<sup>th</sup> to Nov<sup>r</sup> 5<sup>th</sup> 1867  
 on the Ship "Eliza Sham" Master H. Cull  
 Tonnage 696 Built at Glasgow When built 1863. (9 mo)  
 By whom built Stephen Owners C. Sham  
 Port belonging to London Destined Voyage Japan and China  
 If Surveyed Afloat or in Dry Dock Green upper dry Dock and East India Dock

Last Survey, No. \_\_\_\_\_ Port Iron Frame Planked Classed S. A. 1. (10.65.)  
 REPAIRS Now done

Sighted bottom the Yellow metal stripped, Caulked from Keel to metal line and re-sheathed with Yellow Metal on felt

Renewed 160 fath<sup>s</sup> of  $1\frac{9}{16}$  Chain Cable tested at Lloyd's proving house Poplar to 44 tons as Certificate No 2072 1<sup>st</sup> Nov<sup>r</sup> 1867. L. R. Leitch Super<sup>nt</sup>

Memo. Cut of last iron 1 Protuberance Anchor from Bude Dock Lost "Magnum" dated 7<sup>th</sup> Nov<sup>r</sup> 1867. Adm. Test 24 1/2 Tons produced 10/11/67 Bower Anchor deficient, which the Owner has promised to supply Bower Anchor now on board, Nov<sup>r</sup> 16<sup>th</sup> 1867.

## Present Condition of the

Decks	<p><i>Good where seen</i></p>	Transoms <u>Iron lattice metal</u>	<p><i>Good where seen</i></p>	Windlass and Capstan
Waterways		Breasthooks and Stemson		Pumps <u>2 Main &amp; 2 bilges</u>
Comings		Transoms, Pointers, and Crutches		Boats <u>4</u>
Upper Deck Beams & Fastenings		Timbers of the Frame at the openings		Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings		Ditto Ditto at other places		Condition, how ascertained <u>insp<sup>n</sup> and enquiry</u>
Planksheers		Keelsons		Sails
Sheerstrakes		Clamps and Shelves		Anchors No. of _____
Topsides		Ceiling		Cables
Wales		Rudder <u>Ad good</u>		Hawsers and Warps
Plank (Bottom) and Counter		Copper <u>on</u> When put on <u>now</u>		Standing & Running Rigging
General Observations and Opinion,		Caulking of Bottom, Deck, & Waterways. <u>good where tested.</u>		

She is now in good and efficient condition and fit in my opinion to remain Classed. S. A. 1. when the Bower Anchor is supplied. Joseph Allen.

The Amount of Fee.....£ : : is received by me,

Special.....2-2-0

Certificate (if required) : 5 :

Committee's Minute 8<sup>th</sup> November 1867

Character assigned

Raised to 17

To have fig 1

See Adams

See last Survey (B.S.) Fees not paid



© 2021

Lloyd's Register Foundation