

# REPORT of SURVEY for REPAIRS.

28762

No. in Reg. Book. **No.** \_\_\_\_\_ Survey held at London Date Oct 18<sup>th</sup> to 21<sup>st</sup> 1867  
 on the Ship "Thyatira" Master J Ross  
 Tonnage 898 Built at Aberdeen When built 1867  
 By whom built Stood & Owners G Thompson junr  
 Port belonging to Aberdeen Destined Voyage Sydney  
 If Surveyed Afloat or in Dry Dock Union (Dry Dock)

Last Survey, No. 2369 Port Aberdeen Classed 17 A.1.

## REPAIRS

now done,

not yet posted

The bottom sheathed with Gellow Metal on Felt

## Present Condition of the

Decks	good	Treenails Bolts	good	Windlass and Capstan	good
Waterways	good	Breasthooks and Stemson	good	Pumps	where
Comings	good	Transoms, Pointers, and Crutches	good	Boats	seen
Upper Deck Beams & Fastenings	where	Timbers of the Frame at the openings	where	Masts, Yards, &c.	seen
Lower Deck Beams & Fastenings	where	Ditto Ditto at other places	where	Condition, how ascertained by inspection	seen
Planksheers	seen	Keelsons	seen	Sails	good
Sheerstrakes	seen	Clamps and Shelves	seen	Anchors No. of 3 BLS 2H	and
Topsides	seen	Ceiling	seen	Cables	sufficient
Wales	seen	Rudder	seen	Hawsers and Warps	seen
Plank (Bottom) and Counter	seen	Copper T.K.Y.M. When put on	now	Standing & Running Rigging	2

## General Observations and Opinion,

Caulking of Bottom, Deck, & Waterways. good where tested

She is now where seen in good condition fit in my opinion to remain as classed

The Amount of Fee.....£ — : — is received by me,

Special..... : :

Certificate (if required) : :

Committee's Minute 15<sup>th</sup> November 1867

Character assigned 17 A.1

record M



©2021

Lloyd's Register Foundation

LON652-0430